

Appendix B - Photographs




Figure 2 - This image shows the portion of the roof fall that extended back from the unsupported working place through the roof bolts.



Figure 3 - This image shows the perspective from the No.7 entry. The high angled slickensided face (with moist clay layer) of Slip #1 is visible above the miner boom.